




Exposed Slope surface of the Dhalli Rockslide indicating extensively jointed surfaces causing wedge failure





Post landslide field work with the supervisor revealed the settlements and vehicles damaged located along the downside of the slope.





Field work indicating the contour mapping of the landslide sites along with the PhD supervisor and co scholar





Filed work at the Jhakri landslide site indicating the dislodged blocks of rocks along the nearby slope at NH 22



Installation of the autonomous landslide Early warning system as a pilot study with the Research guides